

# BOS Parts List—Pro Solar Mounting Hardware



5/16" (or 3/8") Lag Bolt with Washer  
5/16" x 3/4" O.D. Flat Washer




E-Series Flashing



Slider Nuts



FastJack Base & Standoff  
3/8"-16 x 3/4" Hex Bolt  
3/8" x 1" O.D. Flat Washer



Oatey Flashing



End-Clamp with Hex Bolt  
5/16"-18 x 3/4"  
5/16" Hex Bolt Lock Washer



Solar Wedge Tilt Kit



Deep Channel Rails



Mid-Clamp with Hex Bolt  
5/16"-18 (Various Lengths)  
5/16" Hex Bolt Lock Washer



Tile Trac



Rail Splice  
5/16"-18 x 1-1/4" Hex  
Bolt 5/16" Lock Washer



Cable Clip